

GUARDDO

GUIDE

Specifications.....3

Parts description.....4

Turning on.....5

Disk Destruction.....6

Contacts.....7

TECHNICAL CHARACTERISTICS

Destroys all information on 2.5“ and 3.5” magnetic hard drives irretrievably

Overall dimensions of the working chamber	30.00 x 24.90 x 19.60cm
Strength of the erasing magnetic field in the active part of the chamber	at least 600kA/m
Duration of entering the “Ready” mode after power supply	max. 15s
Minimum pause between repeated starts of the erasing process	20c
Duration of erasing information on one media	max. 0.1s
Activation control via a button on the side panel Duration of operation in Ready mode	not limited
Product power supply	220~240 V 50Hz mains
Current consumption from the mains supply	not more than 3A
Operating temperature range	540C
Relative humidity	up to 70% at t = 25C
Weight	5kg



DESCRIPTION OF PARTS



Power connector



Disk space



Button to destroy a disk

INCLUSION



Connect the power supply



The green indicator will light up

DISK DESTRUCTION



1

Put the disk in the
destruction area



2

Close the disposer cover and press
the disk destroy button

CONTACTS

Click on the app icon and you will have a support chat open up





